


# MEASURING DATA MANAGEMENT SOFTWARE



## SOFTWARE FOR DATABASE COMPUTER CODE 7311-1

**make measurement program**

workpiece information

measuring items

description

measuring tools

set tolerance

measuring code

input port

workpiece drawing

Make measurement program for each one inspection computer. Maximum 200 dimensions can be measured by one inspection computer.

**make data statistics**

process control analysis

CPK analysis

overall equipment effectiveness analysis

**report**

## SOFTWARE FOR INSPECTION COMPUTER CODE 7311-2

**step 1**

Measure the 1st dimension by following the yellow position indication.

**step 2**

Measure the 2nd dimension by following the yellow position indication. The 1st data will be shown in red or green according its tolerance.

**step 3**

Measure the 3rd dimension by following the yellow position indication. The 2nd data will be shown in red or green according its tolerance.

**step 4**

Measure the 4th dimension by following the yellow position indication. The 3rd data will be shown in red or green according its tolerance. The data of four measurements will be sent to the database computer.