LARGE STROKE DIGITAL INDICATOR

DATA OUTPUT

- Button function: on/off, zero, mm/inch
- CR2032 battery, automatic power off
- Data output
- Optional accessory: data output cable (code **7306-40**,**7302-SPC3A**, **7305-SPC1A**), backs (page 101), contact points (page 98~100)

2117-100



spindle lift knob is included

Resolution 0.01mm/0.0005"

Code	Range	Accuracy	Hysteresis	Remark
2117-100	100mm/4"	30μm	10μm	lug back

Resolution 0.001mm/0.00005"

Code	Range	Accuracy	Hysteresis	Remark
2117-1001	100mm/4"	9μm	3μm	lug back