





WIRELESS DATA TRANSFER SYSTEM

| Code | Description | Applicable products |
|---------|-----------------------------|--|
| 7306-1 | receiver (with USB cable) | |
| 7306-2 | receiver (with RS232 cable) | |
| 7306-20 | transmitter |  digital calipers and digital depth gages (not for 1103) |
| 7306-30 | transmitter |  digital micrometers (not for 3631, 3632, 3108, 3109, 3635) |
| 7306-40 | transmitter |  digital indicators |
| | |  digital protractors |

DATA COLLECTION:

- 1) Single collection: press the read button once to collect the reading from measuring tool once.
- 2) Multi collection: press the read button once to start collecting readings from measuring tools continuously, press the button again to stop collecting. Total collection times and interval time can be adjusted.



- DISPLAY: data can be input to Excel as keyboard signal.

All data are displayed in the same column.
Each measuring tool can be coded such as A, B, C, etc.

measuring tools code A, B, C

| | A | B | C | D | E | F | G | H |
|----|---------|---|---|---|---|---|---|---|
| 1 | 10.66-A | | | | | | | |
| 2 | 5.960-B | | | | | | | |
| 3 | 80.03-C | | | | | | | |
| 4 | 25.49-B | | | | | | | |
| 5 | 50.05-C | | | | | | | |
| 6 | 10.56-A | | | | | | | |
| 7 | 25.59-B | | | | | | | |
| 8 | 5.960-B | | | | | | | |
| 9 | 10.67-A | | | | | | | |
| 10 | 80.04-C | | | | | | | |
| 11 | 25.05-B | | | | | | | |
| 12 | 50.03-C | | | | | | | |
| 13 | 5.960-B | | | | | | | |
| 14 | 80.05-C | | | | | | | |



APPLICABLE FOR OTHER BRANDS



- CONNECTION: one receiver can be connected to 30 transmitters.

