

HIGH PRECISION COMPACT DIAL INDICATOR

lifting lever (optional)





Within the measuring range, the spindle is in contact with the lever



lever device

When the measuring range is exceeded, the spindle leaves the lever





Shockproof

- Jeweled bearing
- With limit pointers
- Optional accessory: backs (page 101), contact points (page 98~100), lifting lever (code 6289-150)







2890-1

Code	Range	Graduation	Accuracy	Hysteresis	Range/rev	Dial reading	Remark
2890-1*	1mm	0.001mm	4µm	1.5µm	0.1mm	0-100	lug back
2890-1F*	1mm	0.001mm	4µm	1.5µm	0.1mm	0-100	flat back

^{*}Supplied with manufacturer inspection certificate traceable to NIST USA

