

HIGH PRECISION DIAL INDICATOR

MANUFACTURER

lifting lever (optional)



Shockproof

- Jeweled bearing
- With limit pointers
- Optional accessory: backs (page 101), contact points (page 98~100), lifting lever (code 6289-150)

lever device







When the measuring range is exceeded, the spindle leaves the lever



1	11111111111111111111111111111111111111		100	
		Manhar	Juliun.	1
		289	1-1	

Code	Range	Graduation	Accuracy	Hysteresis	Range/rev	Dial reading	Remark
2891-1*	1mm	0.001mm	4µm	1.5µm	0.1mm	0-100	lug back
2891-1F*	1mm	0.001mm	4µm	1.5µm	0.1mm	0-100	flat back

^{*}Supplied with manufacturer inspection certificate traceable to NIST USA





